Properties belonging to Sri M. Appiah.

Taluk	Hobli	Village	Site No.	Extent Sq. Ft.	Municipal assessment Rs.	Estimated value Rs.
Bangalore North ...	Kasaba ...	Lingarajapura ...	51	58×80	...	32,000
Do	Do	Do	51	58×40	...	16,000

Properties belonging to Sri B. N. Thimma Reddy.

Bangalore North ...	Kasaba ...	Bangalore City Corporation, Gandhinagar.	(1) 185—206	800×30	112	24,000
			(2) 185—287	1250×30	175	37,500
			(3) 185—2—209	360×30	45	10,800
			(4) 185—3—209	500×30	62—8—0	15,000
Do	Do	Do	(5) 40—50	700×30	98	20,000
			(6) 50—1	2000×30	280	60,000
			(7) 50—2	2000×30	280	60,000
			(8) 50—2	2000×30	280	60,000

*All these items have been encumbered to Bank of Mysore, Ltd. and Sri S. H. Kelkara, and the sale is subject to these prior encumbrances of these persons.

Arrears due to Government.

	Rs. a. p.
1. Devanahalli	23,483 0 0
2. Magadi	11,562 7 9
3. Nelamangala	28,314 4 0
Total ...	63,309 11 9

4798

B. C. CHANNARAJ URS,
Sub-Division Officer.

OFFICE OF THE ASSISTANT ENGINEER AND IRRIGATION OFFICER, NO. 2 SUB-DIVISION, BANGARPET, P.W.D., KOLAR DISTRICT.

Notification dated 10th September 1954.

Under Section 29 (1) of the Mysore Irrigation Act as amended and VII of 1938 and VII of 1952, the following Irrigation works with detailed particulars involving levy of water rate and contribution are here by notified for the information of the public concerned. Any representation on the subject from any of the concerned ryots may be preferred before the undersigned in his office during office hours within thirty days from the last date of publication in the *Mysore Gazette*, after which no representation will be entertained.

Sl. No.	Name of Village	Name of Tank	Nature of Work	Tank Sl. No.	Tank Reg. No.	Amount of Estimate.	Amount of Contribution.	Atchkat Kharab Existing Acres	Atchkat Kharab Existing Guntas	Acres	Guntas	Water Rate	Remarks
			KAMASAMUDRAM HOBLI, BANGARPET TALUK.										
1	Kamasamudram	Channegowdanakere.	Closing lease and Strengthening Perculation.	452	...	618	154	6	...	...	...	...	Work Completed.
2	Bathlur ...	Kodagikere ...	Repairs to Sluice and waste weir	664	...	1,437	359	7	6	...	...	...	Do
3	Gattahalli ...	Naranappanakere	Repairs to Sluice and waste weir	196	704	1,860	465	4	...	...	...	...	Do
4	Balamande ...	Koralakere ...	Repairs to Bund and Sluice ...	451	...	2,010	502	9	...	...	...	...	Do
5	Do ...	Nainkere ...	Repairs to Bund and Sluice ...	450	...	900	448	6	...	...	...	...	Do
6	Do ...	Do ...	Earthwork and repairs to weir ...	...	...	890							
7	Bandarahalli ...	Naleygowdanakere.	Repairs to Sluice and weir ...	649	...	2,523	631	6	...	...	...	...	Do
8	Thoppanahalli ...	Kotekere ...	Repairs to Sluice and weir ...	650	460	2,663	1,498	11	...	...	...	...	Do
9	Do ...	Do ...	Construction of C.I. Pipe Sluice and weir.	...	...	3,330							
10	Gullahalli ...	Dasankere ...	Construction of Masonry body wall.	200	...	1,400	350	11	...	...	...	...	Do
11	Gandahalli ...	Krishnankere ...	Repairs to Bund and Sluice body wall.	665	...	767	191	4	...	...	...	...	Work Stop.
12	Bangar Natha ...	Voddu ...	Repairs to Voddu ...	...	...	1,000	250	18	...	...	...	...	Work Completed.
13	Kenduli Mande ...	Voddu ...	Repairs to Voddu ...	...	...	1,300	325	18	...	...	...	...	Do
14	Palamadagu ...	Voddu ...	Repairs to Voddu ...	...	...	2,500	625	18	...	...	...	...	Do
15	Ukkarahalli ...	Neralakere ...	Desilting and Construction of C.I. Pipe Sluice.	105	...	1,674	419	10	...	...	...	...	Do
16	Patha Ramagalla	Kodagekere ...	Providing revetment and waste weir.	191	...	1,755	439	6	...	...	...	...	Do
17	Nadampalli ...	Doddakere ...	Improvements to Bund and Turfing.	635	379	840	210	19	...	...	...	...	Do
18	Muthanur ...	Marappagowdanakere.	Desilting work	...	...	1,900	475	19	...	...	...	...	Do
19	Bodaguruki ...	Earappanakere ...	Desilting and closing leak ...	631	...	1,480	360	5	...	...	...	...	Do
20	Thoppanahalli ...	Chintalkere ...	Desilting and closing leak ...	652	...	2,209	619	11	...	...	...	...	Do
21	Do ...	Do ...	Closing leak	...	...	270							
22	Chinkamanahalli	Deverakere ...	Construction W. Weir and Sluice	659	...	1,650	412	6	...	...	...	...	Final to be done.
23	Janagatta ...	Patharakere ...	Desilting Work	626	369	420	292	30	...	...	...	...	Work Completed.
24	Do ...	Do ...	Do	...	...	150							
25	Do ...	Do ...	Do	...	...	600							
26	Thavarekere ...	Chayappanakere	Do	613	...	675	433	5	...	...	...	...	Do
27	Do ...	Do ...	Constructing Masonry Weir ...	...	...	856							
28	Kadarenahalli ...	Kempiahnakere ..	Desilting Work	441	...	1,6 0	407	7	...	...	...	...	Do
29	Gallahalli ...	Mudivinakere ...	Desilting Work and Construction of Weir and Sluice.	199	...	1,150	862	11	...	...	...	...	Final to be done.
30	Patha Ramagalla	Janganakere ...	Construction of C.I. Pipe Sluice and Core Wall.	194	...	3,415	854	8	...	...	...	...	Work Completed.
31	Madabays to Kamasamudram	Tank Channel ...	No. 1 F. and No. 2, Construction of C.I. Pipe Sluice and Core Wall Madabays.	...	...	6,820	1,705	600	...	...	...	...	1 Work Completed. 2 Final to be given.
32	Providing Additional Cross Bridge.	Kamasamudram Tank and Channel.	Construction of Cross Bridge ...	...	...	3,800	950	...	...	...	...	...	Work Completed.
33	Jakkapalli Gidda Kadarenahalli.	Kamasamudram Tank.	Constructing Wasteweir ...	625	...	1,031	257	6	...	...	...	...	Work Completed.
34	Do ...	Construction of C.I. pipe sluice.	Do do ...	...	...								
35	Doddamaranahalli	Kondaibnakere ...	Closing the leak ...	440	...	400	100	4	...	...	...	...	Do
36	Battarahalli Basavegowdanakere.	Basavegowdanakere.	Constructing C.I. Pipe Sluice ...	672	...	763	191	5	...	...	...	...	Do
			BUDIKOTE HOBLI, BANGARPET TAULK.										
37	Gagiga ...	Puldikere ...	(a) Improvements to Bund ...	462	...	4,823	...	8	...	...	...	...	Completed.
			(b) Resectioning the Bund ...	...	...								
			(c) Desilting the Bund ...	...	...								
38	Junjanahalli ...	Venkata Rao kere	(a) Desilting of Tank ...	421	...	3,800	...	17	...	...	...	...	Do
			(b) Resorting the Tank ...	...	...								
			(c) Improvement to Bund and W. Weir and Sluice.	...	...								
			(d) Gravelling the Slopes ...	...	...								

Sl. No.	Name of Village	Name of Tank	Nature of Work	Tank Sl. No.	Tank Reg. No.	Amount of Estimate.	Amount of Contribution.	Atchkat Existing Acres	Atchkat Existing Guntas	Kharab Acres	Kharab Guntas	Kharab Water Rate	Remarks
39	Banahalli ...	Chintalkunte ...	Improvement to Bund and Wasteweir.	427	...	...	...	...	...	...	...	...	...
40	Do ...	Urumundinkere...	Desilting the Bund Sluice Wasteweir.	...	...	3,058	...	5	...	...	...	...	Completed.
			Closing Perculation Repairing the Pipe Sluice and Wasteweir.	430	...	1,515	...	20	...	...	...	...	...
41	Hunkala Doddi Tank.	Tank ...	Desilting the Tank Improvements to Bund and Wasteweir and Gravelling the Slopes.	431	...	3,117	...	8	...	...	...	...	Completed.
42	Yele Sandra ...	Neerinakere ...	Constructing Silt Dam ...	435	...	960	...	21	...	...	...	...	Do
43	Do ...	Karalakere ...	Improvements to Bund to Restoration, etc.	437	...	3,722	...	6	...	...	...	...	Under Progress.
44	Marandahalli ...	Sampangikere ...	Restoration of Tank ...	207	...	1,793	...	5	...	...	...	...	Do
45	Santiganahalli ...	Tank ...	Do	208	...	3,300	...	5	...	...	...	...	...
46	Yachamanahalli...	Hongekere ...	Do ...	386	...	2,360	...	7	...	...	...	...	Under Completion
47	Ukkunda ...	Gobrakere ...	Improvements to Bund and Sluice, etc.	381	...	2,460	2,460	29	...	...	...	...	Do
48	Muganahalli ...	Voddu ...	Restoration of Voddu. Making good to damages due floods	...	...	6,500	...	30	...	...	...	...	Do
49	Kodaguruki ...	Tank ...	Approach Clearing to Wasteweir	431	...	2,600	...	42	...	...	...	...	Do
50	Do ...	...	Do do ...	...	...								
			TYAKAL HOBLI, MALUR TALUK.										
51	Agara ...	Hongekere ...	Constructing C.I. Pipe Sluice of 6" and in Place of Damaged leaky Sluice.	352	160	784	196	36	30	...	...	...	Do
52	Thotagowdanahalli.	Amanikere ...	Construction R W.W. across W. Weir urgent repairs to Sluice and W.W. and Turfing to Slopes	353	171	1,705 + 1,550	814	87	16	...	...	...	Do
53	Halepalya ...	Giriyappanakere	Closing leaky and urgent repairs to Bund.	495	235	1,600	400	7	25	...	...	...	Under Progress.
54	Panamakanahalli	Doddakere ...	Restoring the Damaged Wasteweir, urgent repairs to Wasteweir and closing leaks in the Bund.	133	186	2,457	614	27	19	...	...	...	...
55	Nidaramangala ...	Chokkanathanakere.	(a) Reconstructing the Damaged Wasteweir.	344	174	3,402	...	55	8	...	...	...	Work Completed.
			(b) Improving the Feeder Channel.	...	...	2,250	...	...	12	...	...	...	Do
			(c) Resectioning the Bund ...	...	...	3,416	...	...	...	...	...	...	Under Progress.
			(d) Raising the Wasteweir ..	...	...	1,300	...	...	...	...	...	...	Do
			(e) Turfing the Bund Slopes ...	...	...	1,500	2,967	...	...	...	...	...	Do
						11,868							
56	Anemittanahalli...	Pamalakunte ...	Repairs to Sluice ...	368	..	339	85	11	12	...	...	...	Completed.
57	Chicknaikanahalli	Rama Rajukere ...	Repairs to Sluice and Closing leaky in the Bund.	387	157	439	109	3	21	...	...	...	Do
58	Doddamale ...	Mainakere ...	Constructing C.I. Pipe Sluice of 6" Dia in place of Damaged leaky one.	316	206	815	204	2	34	...	...	...	Do
59	Do ...	Hosakere ...	Making good the Damages and repairing the Feeder Channel.	317	207	2,482	...	20	36	...	...	...	Do
60	Konda Settyhalli	Mavukere ...	Urgent repairs to Feeder Channel Do to Sluice Wasteweir and Turfing the Slopes.	335	133	1,220	...	11	20	...	...	...	Work Completed.
61	Somasandra ...	Kodagikere ...	Repairs to leaky Sluice and Bund Closing leaks and Scours.	363	229	1,027	412	10	3	...	...	...	Do
62	Yalaraguli ...	Biderkere ...	Constructing a Pipe Sluice ...	323	218	430	108	10	21	...	...	...	Do
63	Ullarahalli ...	Hongekere ...	Repairs to Sluice and Bund ...	355	223	960	240	22	22	...	...	...	Do
64	Banahalli ...	Doddakere ...	Restoring the Bund and Strengthening Bund, etc.	398	189	932 + 2,870	...	20	37	...	...	...	Do
65	Chickamalle ...	Kodagikere ...	Restoration:—	318	205	2,200	950	13	36	...	...	...	Do
			Urgent repairs to Sluice and Wasteweir, Turfing the Slopes.			3,320 + 1,350	1,718	...	...	...	...	...	Under Progress.
66	Byrathanahalli ...	Bandekere ...	Restoring the Damaged Weir, Closing leaky and Improvements	331	200	2,616 + 1,650	1,067	17	26	...	...	...	Do
67	Do ...	Mavukere ...	Closing leaks and repairs to Bund, Raising the Wasteweir.	332	201	2,778 + 950	932	16	3	...	...	...	Completed.
68	Do ...	Nakalikere ...	Constructing Masonry Sluice, etc.	329	202	1,400	350	5	25	...	...	...	Under Progress.
69	Hunisikote ...	Hongekere ...	Strengthing the Bund ...	357	238	4,500	1,125	33	17	...	...	...	Do
70	Kootiganahalli ...	Oorumundinakere	Desilting ...	351	147	4,000	1,000	29	24	...	...	...	Completed.
71	Obatti ...	Hongekere ...	Construction of Wasteweir and Sluice and Desilting.	492	226	3,100 + 3,000	1,525	3	13	...	...	...	Under Progress.
72	Ooriguruki ...	Gondalakere ...	Making Good the Flood Damage Caused to Wasteweir.	3,493	224	3,300	...	15	4	...	...	...	Do
73	Tyakal ...	Sonnenkere ...	Urgent repairs to Sluice ...	364	161	104	...	10	38	...	...	...	Work Completed.
74	Do ...	Easwarakere ...	Restoration	366	162	3,100	...	47	1	...	...	...	Do
75	Hullerahalli ...	Hongekere ...	Restoring	365	223	1,800	...	22	22	...	...	...	Work Under Progress.
76	Seethahalli ...	Doddakere ...	Construction of Silt Dam Extension of Wasteweir.	370	362	3,200 + 1,700	1,225	45	1	...	...	...	Do
						4,900		137	36	...	...	...	Do
77	Huladanahalli ...	Doddakere ...	Urgent Repairs ...	320	369	598	...	...	...	...	...	...	Work Completed.
78	Badamakanahalli	Gare Voddu ...	Repairs to Voddu and Channel ...	...	...	3,950	...	20	...	...	...	...	Do
79	Pudasettihalli ..	Kodagikere ...	Closing leaks and urgent repairs to Sluice and Wasteweir.	325	184	4,250	...	8	38	...	...	...	Under Progress.
80	Tyakal ...	Bendekere ...	Closing leaks in the Bund ...	369	142	1,200	...	16	24	...	...	...	Do
81	Bettahalli ...	Bogadikunte ...	Earthwork to Bund C I. Pipe Sluice and Wasteweir.	407	...	1,900	...	3	33	...	...	...	Do
82	Kenchaganahalli	Tank ...	Repairs to Damaged Wasteweir	351	147	3,400	...	29	24	...	...	...	Do
83	Agara ...	Nagi Reddykere	(a) Closing the leaks in the Bund	539	184	900	...	22	8	...	...	...	Do
			(b) Wasteweir Restoration ...	...	...	1,800	..	...	...	...	...	...	Do
			(c) Strengthening the Bund ...	...	...	850							
			(d) Turfing the Slopes ...	...	...	1,100 + 1,200	1,587	...	...	...	...	...	Do
84	Halepalya ...	Venkatekere ...	Raising the Wasteweir Restoring the Bund.	494	234	1,400 + 850	... 562	23	38	...	...	...	Do
								...	...	...	...	...	Work Completed.

4833

N. NAGAPPA, *Asst. Engr. and Irrigation Officer.*

3-2 B